

Exterior Before – Dirty siding, missing windows, broken door, flaking paint, ugly foundation



Exterior After- replaced windows and door, painted foundation and deck, made shutters, power washed





Bathroom before – Filthy tub surround, decayed subfloor, Rotted vanity, cracked sink



Bathroom after – cleaned tub surround, Replaced subfloor, new tile, new vanity New sink, new fixtures, new toilet



Bed 1 before - plywood floors, no windows, no closet doors



Bed 1 after - new window, new carpet, new closet




Bed 2 before - missing windows, plywood floors



Bed 2 after - new windows, new carpet



Bed 3 before - missing windows, plywood floors



Bed 3 after, new windows, new carpet






Living room before - plywood floors, old windows, odd space



Living room after - tile floors, split into living room and new 4th bedroom



Kitchen before - plywood floor, missing upper cabinets, severely damaged counter tops, no room for washer/dryer



Kitchen after - repaired and painted cabinets, new hardware, new counters, new sink, new upper cabinets over stove, new washer/dryer area, new tile



Kitchen after



Kitchen after

